

ADA Compliance Program

Clark County Facilities Transition Plan Clark County Center for Community Health – 1st Floor

Date of Survey:

April 25, 2006

Conducted by:

Teresa GuiseVern PerryTim McVicker



Item: Drinking Fountain – 1st Floor Protrusion Limits


ANSI 307.2 Protrusion Limits.

Objects with leading edges more than 27 inches and not more than 80 inches above the floor shall protrude 4 inches maximum horizontally into the circulation path.

The drinking fountain shown protrudes 11 inches and the height shown is 32 3/8 inches.



- 1. 1st floor fountains should be recessed into an alcove.
- Barrier's Constructed around fountains






Item: Telephone – 1st Floor – Protrusion Limits - Typical

ANSI 307.2 Protrusion Limits.

Objects with leading edges more than 27 inches and not more than 80 inches above the floor shall protrude 4 inches maximum horizontally into the circulation path.

Recommendations:

- 1. Telephone should be recessed into an alcove.
- Barrier's constructed around telephone





Item: Signage - First Floor (Hallway directory, water closets, and shower rooms)

Issue: Sign location – Signs indicate restrooms are accessible. However, restrooms do not meet code for accessibility.

ANSI Section: Chapter 7

- ANSI 703 Signs Please refer to ANSI standards for complete sign requirements (Accessible and ambulatory)
- ANSI 703.3.11 Location Where a tactile sign is provided at a door, the sign shall be alongside the door at the latch side.
- ANSI 703.3.10 Height Above Floor Tactile characters shall be 48 inches minimum above the floor, measured to the baseline of the lowest tactile character and 60 inches maximum above the floor, measured to the baseline of the highest tactile character.
- Restrooms that do not meet accessibility code, should be identified as ambulatory with signs indicating where fully accessible restrooms are located.



Item - Chairs in Bathrooms

Note: Chairs were placed in bathrooms as a device to place clothing while showering. However, the chairs obstructed accessibility.

IBC Section1109.8.3 – Coat Hooks and Folding Shelves

Where coat hooks and folding shelves are provided in toilet rooms, toilet compartments, or in dressing, fitting or locker rooms, at least one type shall be accessible and shall be provided in accessible toilet rooms without toilet compartments, accessible toilet compartments and accessible dressing, fitting and locker rooms.

Recommendations:

1. Remove chairs and install peg-hooks in all shower rooms




Item – Exposed Pipes in Restroom off Classroom – 1st Floor

Location: 1st Floor Restroom

ANSI 606.6 - Exposed Pipes and Surfaces

Water supply and drainpipes under lavatories and sinks shall be insulated or otherwise configured to protect against contact. There shall be no sharp or



Recommendations:

1. Install pipe coverings



Item: Television Cabinets - First Floor (typical)

Issue: Access to audio components in cabinet.

ANSI Section – 309.4 Operation

Operable parts shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the waist. The force required to activate operable parts shall be 5.0 pounds.

Recommendation:

- 1. Acquire cabinet with latch that can be opened with closed fist.
 - or -
- 2. Acquire shelf cabinet with no doors.



Item: Magazine Rack: - First Floor

Issue: Reach Range

ANSI Section – 308.2.1 Unobstructed

Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the lower forward reach shall be 15 inches minimum above the floor.

Recommendations:

- 1. Remove ottoman from in from of display shelf.
- 2. Lower display shelf.
- 3. Place sign by shelf indicating that clients should ask for assistance if they cannot reach all materials.



Item: Counter Height for Food Service – First Floor Dining Rooms and Break Rooms (Typical)

Issue: Reach Range

ANSI Section – 308.2.1 Unobstructed

Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the lower forward reach shall be 15 inches minimum above the floor. Coffee dispenser handles are at 60".

Recommendations:

- 1. Counter should be lowered to allow access to coffee dispensers
- 2. Sign indicating that clients should ask for help if needed.



Item: Refrigerator in Break Room – 1st Floor

- Cabinet Height 41"
- Reach range to mid-area of highest shelf 60"
- Reach range to coffee dispenser handle on top of cabinet 60"

Issue: Reach Range

ANSI Section – 308.2.1 Unobstructed

Where a forward and side reach is unobstructed, the high forward reach shall be 48 inches maximum and the lower forward reach shall be 15 inches minimum above the floor

Recommendation:

- 1. Refrigerator should be lowered
- 2. Sign indicating that clients should ask for help if needed.



Item: File Cabinet Obstructs Door Swing Clearance

Location: Room #B171

ANSI Section – 404.2.3.1 Maneuvering Clearances at Manual Swinging Doors –

Approach Direction	Door Side	Perpendicular to Doorway	Parallel to Doorway (beyond latch)
From Latch Side	Pull	48 inches	24 inches

Recommendation:

1. Remove portable cabinet

Item: Seating at Tables - No Wheelchair Access

Location: 1st Floor - Evaluation and Treatment Center

IBC Section: 1109.11 Seating at Tables, Counters and Work Surfaces -

Where seating or standing space at fixed or built-in tables, counters or work surfaces is provided in accessible spaces, at least 5 percent of the seating and standing spaces, but not less than one, shall be accessible.

Recommendation:

1. One chair should be capable of being removed to accommodate individuals in wheel chairs.

Item: Clearance - Current distance from wall to wall in water closet is 49"

Location: Restrooms in Detoxification Center

ANSI Section: 604.3.1 Size – The clearance around a water closet 60 inches minimum, measured perpendicular from the sidewall to sidewall, and 56 inches minimum, measured perpendicular from the rear wall, shall be provided.

There are three (3) restrooms in the detoxification center that are identified as accessible. There are an additional two (2) restrooms that are not identified as accessible.

Recommendations:

- Signs should be placed at these restrooms indicating that they are for ambulatory persons with directions to the nearest fully accessible restroom.
- 2. Reconstruct at least one of the restrooms to meet accessibility code. Item: Clearance Current distance from wall to sink is 55"

Location: Restroom In Deaf Addiction Center


ANSI Section: 604.3.1 Size – The clearance around a water closet 60 inches minimum, measured perpendicular from the sidewall to sidewall, and 56 inches minimum, measured perpendicular from the rear wall, shall be provided.

Recommendations:









2. Reconstruct at least one of the restrooms to meet accessibility code.

Item: Shower Accessibility, Grab Bars and Seating

Location:

ANSI Section:

Recommendations:

Item: Signs Do not have Braille

Location: Detoxification Center Restroom

ANSI Section: Section 703.4.4

Braille shall be below the corresponding text (on signs).

Recommendations:

1. Acquire signs with Braille.

Item: Location of Sign

Location: Detoxification Center Restroom

ANSI Section: 703.3.11 Location

Where tactile sign is provided at a door, the sign shall be alongside the door at the latch side. Note: Where there is no wall space on the latch side of a

single door signs shall be on the nearest adjacent wall.

Recommendations:

1. Move sign to larch side of door.

